

Ship Name: **ARHONTISA PINELOPI**
IMO Number: **7371769**
Date Detained: **10/14/2003**
Port: **Savannah, Georgia**

Ship Type: **General Dry Cargo Ship**
Flag: **Panama**
Class Society: **Polski Rejestr Statkow**
Company(s): Owners, Operators or Managers
Overseas Shipping Co. Ltd
Leventis Maritime Co. S.A.

Deficiencies: Code - Category
1499 - Other (Prop. & Aux. Machinery)
0740 - Pumps

1499 - Other (Prop. & Aux. Machinery)
2550 - Maintenance of ship and equipment

Description
Both ships service diesel genertors have excessive exhaust, fuel and lube oil leaks.
The emergency fire pump prime mover has excessive oil and exhaust leaks.
Numerous salt water cooling pipes in the engine room have leak due to
Objective evidence discovered in an expanded ISM examination revealed that the Safety Management System is ineffective. External Audit requested.

Ship Name: **CARIBBEAN EXPRESS**
IMO Number: **7400778**
Date Detained: **10/15/2003**
Port: **Mayaguez, Puerto Rico**

Ship Type: **Passenger Ship**
Flag: **Panama**
Class Society: **Det Norske Veritas**
Company(s): Owners, Operators or Managers
Access Ferries S.A.
Charm Enterprises S.A.
Access Ferries S.A.

Deficiencies: Code - Category
2555 - Documentation

Description
Vessel does not have a valid Safety Management Certificate.

Ship Name:	ELSA	Ship Type:	General Dry Cargo Ship
IMO Number:	8322040	Flag:	Netherlands
Date Detained:	10/17/2003	Class Society:	Lloyd's Register of Shipping
Port:	Houston, Texas	Company(s):	<u>Owners, Operators or Managers</u> Scheepvaartonderneming Elsa BV Holtrade B.V.

Deficiencies:	<u>Code - Category</u> 2525 - Masters responsibility and authority	<u>Description</u> Vessel conducted unauthorized repairs to a fracture in the #3 port fuel tank. There was also a failure to adhere to testing procedures, repair procedures and notification procedures outlined by the vessel's Safety Management
	0615 - Rescue boats	Rescue boat inoperative due to broken fuel
	1499 - Other (Prop. & Aux. Machinery)	No. 2 steering pump malfunctioning and not holding rudder position as designed.
	2510 - Safety and environmental policy	Objective evidence discovered in an expanded ISM examination revealed that the company/vessel has failed to fully implement the requirements of the ISM Code through the Safety Management System. External audit requested.

Ship Name:	FALCON	Ship Type:	General Dry Cargo Ship
IMO Number:	7374400	Flag:	Panama
Date Detained:	10/01/2003	Class Society:	Det Norske Veritas
Port:	N. Charleston, South Carolina	Company(s):	<u>Owners, Operators or Managers</u> Falcon Shipping Limited

Deficiencies:	<u>Code - Category</u> 1730 - Oily-water separating equipment	<u>Description</u> Inoperable oily water separator.
	0740 - Pumps	No. 2 fire pump has a crack in the piping.

Ship Name:	HOEGH MARLIN	Ship Type:	General Dry Cargo Ship
IMO Number:	7516565	Flag:	Bahamas
Date Detained:	10/11/2003	Class Society:	Det Norske Veritas
Port:	Wilmington, North Carolina	Company(s):	<u>Owners, Operators or Managers</u> Hoegh Fleet Services AS Leif Hoegh & Co. Shipping AS

Deficiencies:	<u>Code - Category</u> 0725 - Fixed fire extinguishing installation	<u>Description</u> Firemain wasted and holed throughout it's length..
---------------	---	---

Ship Name:	HYBUR STAR	Ship Type:	General Dry Cargo Ship
IMO Number:	5022302	Flag:	Panama
Date Detained:	10/15/2003	Class Society:	Panama Maritime Documentation
Port:	Miami, Florida	Company(s):	<u>Owners, Operators or Managers</u> St. Maarten Reefers Limited EXPEDITION 2000

Deficiencies:	<u>Code - Category</u> 0230 - Number/composition (manning)	<u>Description</u> Vessel not manned in accordance with the Safe Manning Certificate. Vessel missing one licensed GMDSS operator.
	0820 - Protection machines/parts	Numerous wasted and broken pipes servicing vital systems.

Ship Name:	INDIAN OCEAN	Ship Type:	Bulk Carrier
IMO Number:	8613011	Flag:	Bahamas
Date Detained:	10/08/2003	Class Society:	Det Norske Veritas
Port:	Fernandina Beach, Florida	Company(s):	<u>Owners, Operators or Managers</u> Indian Ocean Shipping Limited

Deficiencies:	<u>Code - Category</u> 0630 - Launch arrangt. for survival craft	<u>Description</u> Port and Starboard Davits would not launch lifeboats.
---------------	--	--

Ship Name:	LA CRUISE	Ship Type:	Passenger Ship
IMO Number:	7716593	Flag:	Panama
Date Detained:	10/27/2003	Class Society:	Det Norske Veritas
Port:	Jacksonville, Florida	Company(s):	<u>Owners, Operators or Managers</u> H. Dewayne Williams LA Cruise, Inc

Deficiencies:	<u>Code - Category</u> 0230 - Number/composition (manning)	<u>Description</u> Multiple seafarers assigned to positions on vessel in accordance with Safe Manning Document do not hold flag State endorsement, and three -month provisional period permitted by STCW 95 I/10-5 has expired.
	0299 - Other (Crew)	Multiple seafers assigned to position on vesels in accordance with Safe Manning Document have not completed approved training in passenger safety.
	0250 - Certif. persons for survival craft	Vessel does not have sufficeint number of deck officers or certificated person to be placed in charge of survival craft.
	0999 - Other (Safety In General)	Excessive oil & debris in engine room bilges.

Ship Name: **LEVENTISA**
IMO Number: **7210240**
Date Detained: **10/27/2003**
Port: **Savannah, Georgia**

Ship Type: **General Dry Cargo Ship**
Flag: **Panama**
Class Society: **Polski Rejestr Statkow**
Company(s): Owners, Operators or Managers
Overseas Shipping Co. Ltd
Arhontisa Maritime LTD.

Deficiencies: Code - Category
2525 - Masters responsibility and authority

Description
Master failed to implement and maintain a properly functioning safety management system, as noted by the crew's failure to utilize procedures for reporting non-conformities within the provisions of the ISM Code.

1499 - Other (Prop. & Aux. Machinery)

Port and starboard generators have leaks on high-pressure fuel lines.

0799 - Other (Fire Fighting Equipment)

Auxiliary fire pump manifold tie-in pipe wasted and holed.

1499 - Other (Prop. & Aux. Machinery)

Make permanent repairs to generator salt water coolers to prevent the discharge of oil prior to operating generators.

2510 - Safety and environmental policy

Company failed to ensure that the ship is manned with qualified and certificated seafarers in accordance with national and international requirements.

2550 - Maintenance of ship and equipment

Company failed to take appropriate corrective action in dealing with maintenance onboard the vessel, specifically, fuel leaks on both generators and wasted salt water piping.

Ship Name: **MSC NICOLE**
IMO Number: **8509387**
Date Detained: **10/08/2003**
Port: **Jacksonville, Florida**

Ship Type: **Containership**
Flag: **Panama**
Class Society: **Det Norske Veritas**
Company(s): Owners, Operators or Managers
Gulmare Holding S.A.

Deficiencies: Code - Category
1499 - Other (Prop. & Aux. Machinery)

Description
Concrete patch on main saltwater cooling piping in between saltwater cooling pump and main system cutout valve.

Ship Name: **OFICINA PORVENIR**
IMO Number: **7402697**
Date Detained: **10/10/2003**
Port: **Galveston, Texas**

Ship Type: **Supply Ship**
Flag: **Mexico**
Class Society: **Germanischer Lloyd**
Company(s): Owners, Operators or Managers
TSM, S.A. DE C. V.

Deficiencies: Code - Category
0740 - Pumps

1730 - Oily-water separating equipment
1735 - Pumping discharge arrangements
1799 - Other (MARPOL Annex I)

Description
Main fire pump had inadequate pressure and vessel only had one pump onboard.

Oily Water Separator was inoperable and in unsatisfactory condition.

Vessel only had one pump installed onboard , none of which are being used for a bilge pump.

Vessel was performing internal transfers of bilge slop from the engine room to the forward peak tank via a portable submersible pump and a fire hose.

Ship Name: **PONTOMEDON**
IMO Number: **8318685**
Date Detained: **10/09/2003**
Port: **New Orleans, Louisiana**

Ship Type: **Bulk Carrier**
Flag: **Cyprus**
Class Society: **Nippon Kaiji Kyokai**
Company(s): Owners, Operators or Managers
Ocean Freighters LTD.
Sunbeam Maritime Ltd.

Deficiencies: Code - Category
0220 - Certificates of competency

Description
The Third Officer does not have a flag state endorsement for his license nor documentary proof from the flag State that one has been applied for.

Ship Name: **RAYS**
IMO Number: **7419391**
Date Detained: **10/06/2003**
Port: **Wilmington, North Carolina**

Ship Type: **Bulk Carrier**
Flag: **Saint Vincent and the Grenadines**
Class Society: **American Bureau of Shipping**
Company(s): Owners, Operators or Managers
Seatex Shipping Company Limited
Narval Shipping Corp

Deficiencies: Code - Category
0735 - Personal equipment - fire fighting

0730 - Appliances (general equipment)

2020 - Fire drills

2025 - Abandon ship drills

Description
Firemans outfit non- water resistant.

Refill/replace SCBA 02 bottles.

Vessel's crew unable to demonstrate proficiency in a satisfactory fire drill.

Vessel's crew unable to demonstrate proficiency in a satisfactory abandon ship

Ship Name: **SHALOM**
IMO Number: **7612280**
Date Detained: **10/06/2003**
Port: **Miami, Florida**

Ship Type: **General Dry Cargo Ship**
Flag: **Panama**
Class Society: **Govt of Listed Flag**
Company(s): Owners, Operators or Managers
Shalom Oceanic, LTD.
MAVACOL Inc

Deficiencies: Code - Category
1581 - Rudder angle indicator
0740 - Pumps

Description
Rudder indicator has a 16 degree deviation.
Main fire pump can't supply sufficient water pressure.

Ship Name: **TOPAZ**
IMO Number: **7702504**
Date Detained: **10/01/2003**
Port: **Mayaguez, Puerto Rico**

Ship Type: **Ro-Ro-Cargo Ship**
Flag: **Mexico**
Class Society: **Bureau Veritas**
Company(s): Owners, Operators or Managers
Morgon Shipping Ltd.

Deficiencies: Code - Category
1730 - Oily-water separating Equipment

Description
Oily water separator inoperable.

Ship Name: **TRADE WIND**
IMO Number: **8014801**
Date Detained: **10/02/2003**
Port: **Corpus Christi, Texas**

Ship Type: **General Dry Cargo Ship**
Flag: **Greece**
Class Society: **American Bureau of Shipping**
Company(s): Owners, Operators or Managers
Atlantic Bulk Carriers Ltd
Tradewind Special Maritiem Enterprise.
Tradewind Special Maritime Enterprise.

Deficiencies: Code - Category
0720 - Fire fighting equipment
1420 - Cleanliness of engine room
2020 - Fire drills

Description
Emergency fire pump inoperable.
Remove excess oil from engine room bilges.
Vessel crew unable to demonstrate proficiency in a satisfactory fire drill.